

Regeneration mixed-bed cartridges DESTILLO D 12 - D 100

Professional regeneration of exhausted, drinking water contaminated, regenerable mixed-bed quality resins. In addition to the service, the regeneration price also includes the replacement of defective O rings, filter hoses and container ventilation. If necessary, these will be exchanged without consultation and without additional costs. Major damage such as e.g. a defective container will only be repaired or replaced after consultation about the additional costs incurred.

The ancillary costs associated with the regeneration such as packaging and transport are not included.

BENEFITS

- Quick and easy processing
- Each regeneration is logged and documented
- Uncomplicated replacement of defective small parts

APPLICATIONS

- Regeneration of Herco mixed-bed cartridges of the DESTILLO series

Regeneration mixed-bed cartridges DESTILLO D 12 - D 100

CONDITIONS OF USE

Regeneration services are due immediately net (without discount).

TECHNICAL DATA OF SERIES

Product name	Description	Item number
Regeneration cartridge D 10-MB	for DESTILLO d10	150 004
Regeneration cartridge D 12dE-MB	for DESTILLO d12 dE (020 001)	150 009
Regeneration cartridge D 17dE-MB	for DESTILLO d17 dE (020 054)	150 028
Regeneration cartridge D 22dE-MB	for DESTILLO d22 dE (020 056)	150 029
Regeneration cartridge D 26dE-MB	for DESTILLO d26 dE (020 058)	150 030
Regeneration cartridge D 46dE-MB	for DESTILLO d46 dE (020 060)	150 031
Regeneration cartridge D 100dE-MB	for DESTILLO d100 dE (020 007)	150 015