

Regeneration

mixed-bed cartridges DESTILLO D 12 - D 100

Professional regeneration of exhausted, drinking water contaminated, regenerable mixed-bed quality resins. In addition to the service, the regeneration price also includes the replacement of defective O rings, filter hoses and container ventilation. If necessary, these will be exchanged without consultation and without additional costs. Major damage such as e.g. a defective container will only be repaired or replaced after consultation about the additional costs incurred.

BENEFITS

- Quick and easy processing
- Each regeneration is logged and documented
- Uncomplicated replacement of defective small parts

APPLICATIONS

- Regeneration of Herco mixed-bed cartridges of the DESTILLO series

Regeneration

mixed-bed cartridges DESTILLO D 12 - D 100

CONDITIONS OF USE

Regeneration services are due immediately net (without discount).

TECHNICAL DATA OF SERIES

Product name	Description	Item number
Regeneration cartridge D 10-MB	for DESTILLO d10	150 004
Regeneration cartridge D 12dE-MB	for DESTILLO d12 dE (020 001)	150 009
Regeneration cartridge D 17dE-MB	for DESTILLO d17 dE (020 054)	150 028
Regeneration cartridge D 22dE-MB	for DESTILLO d22 dE (020 056)	150 029
Regeneration cartridge D 26dE-MB	for DESTILLO d26 dE (020 058)	150 030
Regeneration cartridge D 46dE-MB	for DESTILLO d46 dE (020 060)	150 031
Regeneration cartridge D 100dE-MB	for DESTILLO d100 dE (020 007)	150 015